

Nak 6708 Open Car Floor repairs

March report 2013

Jim Blyde.

This report is to be conjunction with Bill's report

- March 30th
- Between Noel, Carl and myself we measured where the floor had to be repaired, cut material to fit and weld in place after the hole was cut.
- Under the tuition of myself, I try to teach Carl of what I know of welding to which I think that he has mastered the art some what. Needs a bit practice in the art and also of preparation. As some of us older generation getting a bit older we need to try and bring the younger members up with our knowledge to help with continuation of the Society. This I have seen with other members.
- The floor although was ground there was still some difficulty with slag coming to the surface which made the welding difficult.
- The job is not complete yet but is safe to walk on. I did a test by jumping on the replacement plate and obviously, (Well some one has got to say it), I did not fall through the hole.
- I have asked Carl if could complete this task next weekend, again under my tuition.





All photos copyright to Jim Blyde 2013