

JIM BLYDE'S REPORT
FEBRUARY 2014

- 1 -

My hours worked so far on Tr 407;- $42.5 + \underline{5} = 47.5$, + $\underline{4.5} = 52$ + $\underline{1.5} = 53.5$ + $\underline{16} = 69.5$

I have been busy with other tasks and with computer problems I have not been able to keep up with my report.

I have not taken any photos for February but Neville had taken some which I have asked him to mail them to me.

Between Carl and my self we have got the ditch lights working both front and rear. The rear front and rear ditch lights have been sealed and on the rear wall.

The wiper motors work of the one switch at the moment.
Carl is going to get new blades and one arm.

Have checked the head lights and they are working well, both hi and low. The front reflector will need replacing to illuminate the road ahead.

