

# Dsa 414 Restorations

November Monthly report 2012

Jim Blyde.

This report is to be in conjunction with Bill's report

11<sup>th</sup> November.

With the assistance of Sir Carl Mc we managed to remove the two air filters for the compressors. In the process there was some damage to the rods holding the assemblies together. These will have to be replaced of course.

The fan shroud was removed and the bolts are in a plastic jar left in the engine room front left.

The “V” belts all are now removed and Sir Carl has obtained some pricing for the same which will be passed to committee for approval for payment.

Bill came along to assist with the sand traps and cleared the sand from the front left container. In the process I made up a scrapper to assist in the poking of the sand through the bottom hole, once the sand trap was removed. The top for the container the handle requires welding.

